

Release Notes DM705-SUB 23.1

April 2016, Eldorado do Sul - Brazil

Dear customer,

DATACOM is glad to present DM705-CPU128 firmware version 23.1. Below are listed the new features:

Firmware Upgrade Procedure

- For firmware upgrades from version 22.1 (or less) to 23.x, it is required to perform a two-stages procedure, performing an upgrade to an intermediate version and then to the newest version.

Upgrading firmware stages:

Stage 1: firmware upgrade from version 22.1 (or less) to 22.2 with subsequent reboot.

Stage 2: firmware upgrade from version 22.2 to 23.x with subsequent reboot.

Any doubt about the procedure above, get contact with DATACOM Technical Support.

New Features and Improvements

- SSH connection.
- SNMPv3.

Management

- FW23.1 is fully supported by DmView version 9.1 or higher.

This new version will be available from April 2016. Additional information can be obtained by contacting DATACOM support (support@datacom.ind.br or +55 51 3933-3122).

Regards,
DATACOM